# Monitor calibration tutorial

When editing and reviewing images and visual effects, it's important to work with a calibrated monitor. Calibration ensures you get the truest representation of colors and luminance your monitor can display. Usually, the process consists of either tweaking your monitor's settings, or generating a color profile that your computer applies on the displayed image.

Calibration is often overlooked or considered unnecessary, because players don't play on calibrated monitors or TVs. Even though this is generally true, it's good development practice to create and edit your images in the best conditions you can get. Working on a biased monitor only adds more bias to what the player sees when they play the game on their own screen.

Calibration is also essential when working with a team or artists or developers. It keeps your visual workspace consistent, ensuring that everyone looks at the game in the same conditions and keeps the aesthetic the same across several artists' work.



This page takes you through the steps of calibrating your screen using the **i1 Display Pro** from X-Rite. This device covers a good range of display technologies, and offers a quick and efficient calibration process.

It costs around 230 EUR / 250 USD (price quoted October 2016). It runs on macOS and Windows, and is compatible with some apps on Linux (please note Unity has not extensively tested the device on Linux).

# Step-by-step guide

### Set-up

- 1. Make sure that your monitor has been switched on for at least half an hour. This is necessary because the monitor's display colors might change as it warms up.
- 2. Go to your **Display Settings** and set your monitor to its native resolution. On Windows, this is the **(Recommended)** option; on macOS, it's the **Default for display** option.

Windows 10 :	OsX 10.11 :
Resolution	O O O O D D D D D D D D D D D D D D
2560 × 1440 (Recommended) V	Display         Color           Resolution:         • Diduta for display           Scaled         Brightness:           • Automatically adjust brightness
	AirPlay Display:     Off     ©       If Show mirroring options in the menu bar when available     ?

- 3. Reset the monitor to its factory settings.
- 4. Disable any color-shifting applications (such as f.lux).
- Make sure that your current ambient light conditions roughly represent your average working day conditions (for example, don't calibrate in total darkness if you always work with the lights on).
- 6. Make sure your image editing applications are using the right color space:
  - Adobe Photoshop
  - a. In Adobe, go to Edit > Color Settings
  - b. Under Working Spaces, set RGB to sRGB IEC61966-2.1, and set Gray to sGray
  - c. Under Color Management Policies, tick the checkboxes for Ask when Opening and Ask when Pasting. This allows you to choose what to do with images which

- Step-by-step guide
  - Set-up
  - Calibration
  - Advanced calibration
    - Quality check
    - Refining your
    - calibration
    - Calibration frequency
    - TV Calibration
    - Troubleshooting
    - Windows color management issues

are not color managed or which are saved in a different color space.

d.	Color Settings	×
u.	Settings:       Conversion Options         Ødis:       @RGB IEC01966-2.1         Intent:       Relative: Colorimetric:         Intent:       Relative: Colorimetric:         Ødis:       Des Dither (8-bit/channel images)         ©       Color Management Policies         RGB:       Preserve: Embedded Profiles         Grag:       Preserve: Embedded Profiles         Grag:       Preserve: Embedded Profiles         Ødis:       Ødis:         Ødis:       Ødis:         Ødis:       Ødis:         Ødis:       Ødis:         Ødis:       Ødis:         Ødis:       Ødis:	OK Reset Load Save
	Missing Profiles: Ask When Opening         Wissing Profiles: Ask When Opening         For more information or color settings, search for "setting up color management" in searchable from any Creative Cloud application.         Description         GIMP 2.8.18 (Windows)         Go to Edit > Preferences > Color Management	

- а b. Set Mode of operation to Color managed display
- c. Set **RGB Profile** to **sRGB IEC1966-2.1** (this can be found in
- windows\system32\spool\drivers\color) d. Tick the checkbox for **Try to use the system monitor profile**

W Preferences			×
Environment interface	Color Management		
Help System	<u>M</u> ode of operation: <u>R</u> GB profile:	Color managed display sRGB IEC61966-2.1	
음수 Tool Options 률 Toolbox	<u>C</u> MYK profile:	None	~
Default Image     Default Grid	<u>M</u> onitor profile:	None Iry to use the system monitor profile	~
<ul> <li>Image Windows</li> <li>Appearance</li> </ul>	<u>D</u> isplay rendering intent: <u>P</u> rint simulation profile:	Perceptual	~
🔚 Title & Status 🗾 Display	Softproof rendering intent:	Perceptual	~
Color Management	File Open behaviour:	Mark out of gamut colors  Ask what to do	
Input Controllers	File Open benaviour:	Ask what to do	· · ·
Folders			
Help		<u>R</u> eset <u>Q</u> K	<u>C</u> ancel

### Calibration

The i1 Display Pro comes with its own software, i1Profiler. You need to set this up before you can start profiling and calibrating your monitor.

- 1. Install i1Profiler and the sensor's drivers from the disc, or from the X-Rite website
- 2. Launch i1Profiler
- 3. Under User Mode, select Advanced



### Basic / Advanced mode

**Basic** mode provides all the most significant settings. However, in this tutorial we want to use two features that are only available in **Advanced** mode. If you only want to know about the most commonly-used settings, feel free to stick to **B asic** mode.

4. In the left panel, select **Display > Profiling** to open the **Display Settings** panel:



#### 5. In the Display Settings panel :

- a. Click the display icon representing the display you want to calibrate (see box a in the image below). If you have multiple monitors, be aware that they are not always shown in the right order for example, the icon on the left might represent the monitor on your right. To make it clearer for you, i1Profiler centers the application window on the display you have selected to be calibrated.
- b. In the drop-down list under the display icon, select the technology your display is using (see box **b** in the image below). If you don't have the technical specifications of your monitor, you can usually find them on the manufacturer's website, or on specialized review websites. If you cannot find the information, choose "generic".
- c. Set the White Point to CIE Illumiant D65. This is a widely used standard that makes your whites match an average daylight color, and makes sense if you work mostly during the daytime.
- d. Set the Luminance to 120 cd/m<sup>2</sup>. This represents the brightness of your whites. 1 20cd/m<sup>2</sup> is a common standard when working on images that are to be displayed on a screen (darker whites, between 80-100 cd/m<sup>2</sup>, are recommended when working on images that are to be printed).
- e. Set the **Tone Response Curve** to **sRGB**. This ensures good compatibility with your color-managed applications (such as Adobe Photoshop).



 Under Display Profiling Workflow, select Profile Settings. Set the ICC Profile Version t o Version 2. This ensures better compatibility with your system and applications.

i1Profiler		-	
Assets	Profile Settings		
<ul> <li>Diploy Settings Castan-Apd Popul Soft-Food 201.dpd Popul Soft-Foo</li></ul>	Portule Profile Settings <ul> <li>Lee defaults</li> <li>Wandfrid (default)</li> <li>Profile Version:</li> <li>Profile Version:</li> <li>Profile Type:</li> <li>Wanne bladed (default)</li> <li>Profile Type:</li> </ul>		
	Page Data Load Save	(	Previous Next
	Dopley Profile       Image: Settings       Profile Settings       Path set       Measurement       ICC Profile	Display QA 🥥	
™ :		Load Workflow Se	······ ave Workflow

- 7. Under **Display Profiling Workflow**, select **Measurement** and make the following changes:
  - a. Tick the checkbox for **Adjust brightness, contrast, and RGB gains manually** (s ee box **a** in the image below)
  - b. Click **Start Measurement** and follow the on-screen instructions (see box **b** in the image below)



8. When you click Start Measurement, the calibration process begins. The first window that opens is Profile My Display. Here, tick the checkbox for each setting that you are able to manually adjust through your monitor's built-in settings. You should usually be able to adjust Contrast and Brightness. Make sure you know how to make these adjustments; you will need to be able to do this during calibration. Set the i1 Display Pro sensor against the screen as show in its instructions. Make sure the sensor has good contact with the screen, then click Next.



calibrate this setting. It's good practice to go into your monitor's built-in settings and set each color channel to a lower value than its maximum (for example, 95 if the maximum is 100), so that you have room to adjust them to a higher value if **i 1Profiler** asks you to during the next step.

<u>ی</u>	
White Point Adjustment	
Quality Indicator	
▲	
R G B	
م م م	
the or ange lines are placed in the middle of the green areas. If your display cannot be adjusted, i 1Profiler will automatically match the target white point when building the profile. When you are finished making adjustments (or if your display does not have RGB controls), press "Next" to continue.	
Target: 6502 K x: 0.313 y: 0.329	
Current: 7580 K x: 0.296 y: 0.322	
← Previous Next →	
Profile My Display	
White Point Adjustment	
Quality Indicator	
<b>E 3</b>	
·	
R G B	
R G B Adjust your display's Red, Green and Blue controls until the orange lines are placed in the middle of the green areas. If your display cannot be adjusted, i1Profiler will automatically match the target white point when building the profile. When you are finished making adjustments (or if your display does not have RGB controls), press "Next" to continue.	
Adjust your display's Red, Green and Blue controls until the orange lines are placed in the middle of the green areas. If your display cannot be adjusted, i IProfiler will automatically match the target white point when building the profile. When you are finished making adjustments (or if your display does not have RGB controls), press	
Adjust your display's Red, Green and Blue controls until the orange lines are placed in the middle of the green areas. If your display cannot be adjusted, i1Profiler will automatically match the target white point when building the profile. When you are finished making adjustments (or if your display does not have RGB controls), press "Next" to continue.	

### Laptop calibration

It is possible to calibrate a laptop monitor. In Profile My Display, tick only the Br

**ightness** checkbox (this is usually the only property you can manually adjust on a laptop monitor). Later, when you need to adjust the brightness, try to get as close as possible to the profiler's suggested **120cd/m<sup>2</sup>** with the steps your laptop offers you. If you can't get close enough to get the green icon, aim at the brighter value closest to **120cd/m<sup>2</sup>**. The **i1Profiler** then adjusts the white in the color profile.

Calibration done this way is only accurate when the laptop is set to the same level of brightness, so it's recommended that you remember how you set up your monitor during the calibration, then use the same settings when working on your game.

- 9. When you click **Next**, the **i1 Display Pro** device begins taking measurements. During this process, **i1Profiler** asks you to adjust some settings manually on your monitor. Follow the instructions on the screen.
- 10. When the measurement has finished, go to ICC Profile
  - a. Name your profile (it's recommended to give a name which indicated the monitor that has been calibrated, and the date of the calibration).
  - b. Click Create and save profile. This profile is now applied automatically.

A i1Profiler			-		×
Assets	in the second	IC Profile			
	Default Honsurement  Profile toring  Profile  Profile Profile Profile Profile	Check Beller Berger energing our rest print.			×
	Diçuky Settings Polfa Settings Path est Pleasement IC Polfa				
™ <sub>M</sub> III ? Ѽ Pul Screen Assets Help Home			ad Workfow	:[4] Serve Workflow	

#### Before and after comparison

When a new profile is created, the right part of the window changes to display the results of the calibration. This visualisation also shows a before and after comparison mode, featuring example photographs. To access this, select the small head-and-shoulders box (highlighted in the below image).



Change the photograph using the dropdown (see box  $\mathbf{a}$  in the image below), and use the two switches on the right (see circles  $\mathbf{b}$  in the image below) to compare before and after effects.



# Advanced calibration

This calibration can be refined and improved using the advanced techniques laid out in this section. These techniques may be useful if you are not satisfied with the results of the calibration, or if you just want to check the quality of your calibration.

## **Quality check**

1. In i1Profiler, click the Home button



2. In the left panel, go to Display > Quality

भ i1Profiler		
	Workflow Selector	
Display		T
Profiling		
Quality		
Uniformity		

3. Under **Display Profiling Workflow**, select **Reference**, then click on your display's icon to center the **i1Profiler** window on the correct display

Assets		Display QA Reference	
Reference Patch Sets	🧳 DELL U2715H2016-09-19 left		
	Select your display and technology type		
	DELL U2719H DELL U2719H(2) GH85D6530X1S GH85D6530RFS		
	White LED + White LED +		
	Current display profile: DELL U2719H2016-09-19 left.icm		
	Patch Set Type: Standard		
	Industry Standard Targets: XRite ColorChecker & Classic		
			_
			_
			_
			$\sim$
	Page Data Load Save		Home Net
	😴 Display QA Workflow		
	Reference Heasurement QA Report Tending	rothe any G registra Agrady G	
™a := ? 10 Full Screen Assets Help Home			

4. Under Display Profiling Workflow, select Measurement, then click Remeasure (or Start Measure, if this is the first one).



- 5. Follow the instructions on your screen
- 6. Under Display Profiling Workflow, select QA Report. Hover over each colour in the panels to see a DeltaE value corresponding to that color displayed in the data below (see lower box in below image). The DeltaE value represents how much the color captured on your monitor diverges from the reference color. Ideally, all the colors' DeltaE would be below 2. If you have many colors whose DeltaE is above 4, you should refine your calibration.

ilProfiler			- 🗆 ×
Assets C	# DELL U2715H2016-09-19 left	Report	
Reference Patch Sets	DELL U2/15H2016-09-19 RFT Data Set     Reference: ColorChecker@ 24 P     Measurement: Completed	Patch	
	Result PASS		
	ΔΕ Type ΔΕ 1976 - Average ΔΕ Threshold:		
	Average ΔE results         Measured (Patches)           All petchess         0.85         (24)           Of the lowest 50%:         0.62         (22)           Of the highest 10%:         3.36         (2)	Tdurance 13 © : :	
	Standard deviation results         All potches:         0.95         (24)           Of the lowest 00%:         0.37         (22)           Of the highest 10%:         1.59         (2)           Haximum ΔE results         1.59         (2)		
	Al patches: 4.95 (24) Of the lowest 50%: 1.76 (22)		
		Data Set A 1166.68 at 16.47 bt 17.45 Data Set 8 1166.57 at 16.34 bt 17.44	DetaE: 0.165
		Save report	Add to Trending
	Tonalau CA Maddau		Previous Next
	Reference Heasurent QA Report	Potlemy o Potlemy o Potlemy o Potlemy o	
5 <sub>31</sub> III <b>? Ѽ</b> Full Screen Assets Help Home			

# **Refining your calibration**

If you are not satisfied by your calibration, and all steps of this guide have been carried out, there are two relatively simple ways to do a more in-depth calibration :

- 1. At **step 8** of the guide, tick the checkbox for **RGB Controls**. This helps to achieve better native colors.
- 2. After step 6 of the tutorial:
  - a. Under Display Profiling Workflow, go to Patch Set
  - b. Set Patch set size to Medium or Large



This makes the measurement process longer by measuring a broader range of colors, which creates a more accurate profile.

# **Calibration frequency**

We recommend that artists calibrate their monitors regularly. Calibration should be done every 3-6 months in order to keep good colour consistency.

- For TN and VA monitors, we recommend re-calibrating every 3 months
- · For LED and IPS monitors, we recommend re-calibrating every 6 months

# **TV Calibration**

If you are deploying your game to a video game console, your testing TV should also be calibrated correctly. If you can access the web from your TV (or a device connected to your TV), go to lagom. nl and follow the instructions on the website for a good calibration process.

The best resource of information for calibrating TVs is often a specialized website avforums.com, which reviews TVs and maintains a YouTube channel of videos showing the best picture settings for many TV models, and how to calibrate your TV yourself.

Xbox One has its own integrated calibration tool. See Microsoft's documentation on How to adjust the display settings on your Xbox One console to learn more.

# Troubleshooting

### Windows color management issues

Sometimes, Windows doesn't apply the correct color profile when you restart your computer or when your monitor is disconnected and reconnected. To fix this: 1. Go to **Start menu** > **Run** and type "colorcpl"

		a program, folder, document, or Inter dows will open it for you.
Open:	colorcpl	
	ОК	Cancel <u>B</u> rowse
		dropdown (if you have several displays,
entify mo	ent button to see w	/hich monitor is which).
Devices All Profiles		
Device:	Display: 1. Generic PnP Monitor - N	VIDIA GeForce GTX 1080
<u>v</u> ence	✓ Use my settings for this device	Identify monitors
	ed with this device:	
Name ICC Profiles —		File name
	0160919right.icm (default)	DELL U2715H20160919right.icm beforeProfile.icm
	ight 2016 09 14.icm ight 2016-09-19.icm	beforeProfile.icm DELL U2715H right 2016-09-19.icm
<u>A</u> dd	Remove	Set as Default Profile
		Set as Default Profile
	Bemove olor management settings	
<u>Understanding</u> co	olor management settings	Prgfiles
Understanding co	olor management settings	Profiles Cose
Understanding co elect the c	olor management settings correct color profile in the	Prgfiles
Understanding of elect the c	oler management settings CORPECT COLOR PROFile in the ent	Profiles Coor ne list, and click Set as Default Profile ×
Understanding co elect the c	clor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN	Profiles Cose ne list, and click Set as Default Profile ×
Understanding of elect the c	oler management settings CORPECT COLOR PROFile in the ent	Profiles Coor ne list, and click Set as Default Profile ×
Understanding of elect the c Color Managem Devices All Profiles Device:	clor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN	Profiles Cose ne list, and click Set as Default Profile ×
Understanding co elect the c Color Managem Device: Profiles associate Name	clor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Lise my settings for this device	Profiles Cose ne list, and click Set as Default Profile ×
Understanding co Slect the C Color Managemu Devices All Profiles Device: Profiles associate Name ICC Profiles	clor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Lise my settings for this device	Profiles Cose The list, and click Set as Default Profile VIDIA GeForce GTX 1080 VIDIA GeForce GTX 1080 VIDIA GeForce GTX 1080
Understanding co elect the c color Managem Device: Profiles associate Name ICC Profiles DELL U2715Hr20 DELL U2715Hr20 DELL U2715Hr20	olor management settings correct color profile in th ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 20160919right.icm (default) ght 2016 09 14.icm	Profiles Cose the list, and click Set as Default Profile VIDIA GeForce GTX 1080 Identify monitors File name DELL U2715H20160919right.icm beforeProfile.icm
Understanding co elect the c color Managemu Devices All Profiles Device: Profiles associate ICC Profiles - DELL U2715H ci DELL U2715H ci DEL U2715H c	color management settings correct color profile in th ent Advance Display: 1. Generic PnP Monitor - NN Q Use my settings for this device ed with this device: D100919/njht.icm (default)	Profiles Cose The list, and click Set as Default Profile VIDIA GeForce GTX 1080 VIDIA GEFOR
Understanding co elect the c color Managemu Devices All Profiles Device: Profiles associate ICC Profiles - DELL U2715H ci DELL U2715H ci DEL U2715H c	olor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 2009199/ight.icm (default) ight 2016-09 14.icm gift 2016-09 14.icm	Prgfiles Cose the list, and click Set as Default Profile VIDIA Geforce GTX 1080 VIDIA GEforce GTX
Understanding co elect the c color Managemu Devices All Profiles Device: Profiles associate ICC Profiles - DELL U2715H ci DELL U2715H ci DEL U2715H c	olor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 2009199/ight.icm (default) ight 2016-09 14.icm gift 2016-09 14.icm	Prgfiles Cose the list, and click Set as Default Profile VIDIA Geforce GTX 1080 VIDIA GEforce GTX
Understanding co elect the c color Managemu Devices All Profiles Device: Profiles associate ICC Profiles - DELL U2715H ci DELL U2715H ci DEL U2715H c	olor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 2009199/ight.icm (default) ight 2016-09 14.icm gift 2016-09 14.icm	Prgfiles Cose the list, and click Set as Default Profile VIDIA Geforce GTX 1080 VIDIA GEforce GTX
Understanding co elect the c color Managemu Devices All Profiles Device: Profiles associate ICC Profiles - DELL U2715H ci DELL U2715H ci DEL U2715H c	olor management settings correct color profile in the ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 2009199/ight.icm (default) ight 2016-09 14.icm gift 2016-09 14.icm	Prgfiles Cose the list, and click Set as Default Profile VIDIA Geforce GTX 1080 VIDIA GEforce GTX
Understanding co elect the c Color Managem Device: Profiles associate Name ICC Profiles DELL U2715H ri DELL U2715H ri DELL U2715H ri DELL U2715H ri DELL U2715H ri	olor management settings correct color profile in th ent Advanced Display: 1. Generic PnP Monitor - NN Use my settings for this device ed with this device: 2016/0919/njpht.icm (default) ght 2016-09-19.icm ght 2016-09-19.icm Bernove	Profiles Coore the list, and click Set as Default Profile VIDIA GeForce GTX 1080 Identify monitors File name DELL U2715Hright 2016-09-19.icm DELL U2715Hright 2016-09-19.icm OELL U2715Hright 2016 09 14.icm
Understanding co elect the c color Managem Device: Profiles associate Name ICC Profiles DELL U2715Hri DELL U2715Hri DELL U2715H ri	olor management settings correct color profile in th ent Advanced	Prefiles Close the list, and click Set as Default Profile VIDIA GeForce GTX 1080 Jdentify monitors File name DELL U2715H right 2016 09 14.cm
Understanding co elect the c Color Managem Device: Profiles associate Name ICC Profiles DELL U2715H ri DELL U2715H ri DELL U2715H ri DELL U2715H ri DELL U2715H ri	olor management settings correct color profile in th ent Advanced	Prgfiles Cose the list, and click Set as Default Profile VIDIA GeForce GTX 1080 [dentify monitors File name DELL U2715H20160919right.icm beforeProfile.icm DELL U2715H right 2016-09-19.icm DELL U2715H right 2016 09 14.icm

4. If you don't see a change immediately, you might need to restart your computer to use the new default color profile.

